

Operating instructions digital max-min thermometer indoor/outdoor no. 29570 Kat.no. 30.1020

The digital max-min thermometer is an electronic precision measuring instrument to determine indoor and outdoor temperature as well as the respective maximum and minimum temperatures

measuring range: outside -50 °C/+60 °C (-58 F/+140 F)

inside: -10 °C/+50 °C (+14 F/+122 F)

It is possible to change the reading from Celcius to Fahrenheit by moving a switch at the back of the instrument.

Installation:

The thermometer should be positioned near a window using the built-in hanging slot with a nail or screw. Lead the cable together with the sensing element through the window sealing material to the outside. (Take care of sharpedged window frames without seals).

Operation:

A. Top display

- 1 The thermometer shows the present outdoor temperature.
2. When pushing the 'max-min' button, the maximum temperature appears which has been reached since the last resetting
3. Pushing the 'max-min' button again, the minimum temperature appears which has been reached since the last resetting
4. To recall the present outdoor temperature on the display again, push the 'max-min' button once more
5. Now reset the max-min memory to the present temperature using the reset button.

B. Lower display

1. Show you the present indoor temperature.
- 2-5. As described under 'A', you can recall indoor maximum and minimum temperatures and reset the memory.

**PLEASE DELIVER USED BATTERIES TO THE SPECIAL COLLECTING POINTS.
NO GUARANTEE IF THE INSTRUMENT IS HANDLED OR OPENED
IMPROPERLY!**